

Leveelogger Gold

Firmware Update Release

November 1, 2006

The Leveelogger Gold has been designed with firmware that is easy to update whenever useful new functions or other improvements become available, as with software releases.

It would be useful for owners of Leveelogger Gold units to update the firmware in all their Leveeloggers, at a suitable time.

To update the firmware in your Leveelogger Gold, go to the Solinst Website at: <http://www.solinst.com/Downloads/> where you can complete a brief download form that will provide you with a link to the Leveelogger Gold firmware update file called LL2-V1.016.zip

- 1) Open the Solinst Firmware Update Utility (LLGfirmwareUpdate.exe), which is located in the 'Utility' folder in the Leveelogger3 folder, and pick the COM port to which the Leveelogger is connected. Make sure the Baud Rate is set to 9600.



- 2) Click the leftmost 'Open' button, which should open a file dialog asking for the firmware file (*.ssf) to upload. Navigate to the directory where the firmware file is located then click on the file and click 'Open'.
- 3) Check the 'Firmware File Information' box to make sure that the opened file is the right one.
- 4) Click the 'Upload Firmware' button, which is the second button from the left, to start the firmware upload process.
- 5) If a communication error occurs and is indicated in the Leveelogger Information Window either before the "Verified Program Checksum" message or after the "Program Information Section", then restart the upgrade process.
- 6) If, however, a communication error occurs between the "Verified Program Checksum" and the "Program Information Section" messages, then please contact Solinst. You will need to give the Leveelogger Serial Number and explain the exact positioning of the error message.

Note: When conducting a firmware update, DO NOT interrupt the process prior to completion (This may take 2 – 4 minutes) . If the notice "The firmware version in the Leveelogger is more recent, continue the firmware update?" appears, you must select "Continue". Selecting "No" or otherwise interrupting the Update process will make the Leveelogger unable to communicate with Leveelogger software. To correct this, the firmware must be re-updated, and allowed to fully complete installation. Installation is not complete until a note appears at the base of the program window indicating "Firmware Update Complete".

Solinst Canada Ltd.
1 (800) 661-2023 1 (905) 873-2255

Solinst® **Leveelogger®**
Model 3001